

6335 Applecross Avenue



(Exterior walls with excessive holes, cracks and rotted boards which permit air or water to penetrate)

6335 Applecross Avenue



(Platforms and/or steps shall be provided to serve exits and shall be maintained in a safe condition)

6335 Applecross Avenue



(Exterior wall finish not weathertight without excessive holes, cracks)

6335 Applecross Avenue



(All exterior finish shall be weathertight without excessive holes, cracks or rotted boards which permit air or water to penetrate rooms.)